

Cookies on MOT history service

We use some essential cookies to make this service work.

We'd like to set additional cookies so we can remember your settings, understand how people use the service and make improvements.

[Accept additional cookies](#)

[Reject additional cookies](#)

[View cookies \(/cookie-preferences\)](/cookie-preferences)



Check MOT history

Help us make this service better. Give us your [feedback \(https://www.smartsurvey.co.uk/s/GIZZX?vrm=SK60USP&make_result=KIA&model_result=RIO&mot_first_used_date=2010-09-24&vehicle_age=5526&mot_expiry_date=2026-10-02&mot_expiry_date_days_left=326&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV\)](https://www.smartsurvey.co.uk/s/GIZZX?vrm=SK60USP&make_result=KIA&model_result=RIO&mot_first_used_date=2010-09-24&vehicle_age=5526&mot_expiry_date=2026-10-02&mot_expiry_date_days_left=326&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV).

[< Back](#)

SK60 USP KIA RIO

[Check another vehicle \(/\)](#)

Colour
Silver

Fuel type
Petrol

Date registered
24 September 2010

MOT valid until
2 October 2026

[Get an MOT reminder \(https://www.gov.uk/mot-reminder\)](https://www.gov.uk/mot-reminder) by email or text.

[Download test certificates \(/enter-document-reference?registration=SK60USP\)](/enter-document-reference?registration=SK60USP)

You can [get information corrected on your MOT history \(https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes\)](https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes) (such as mileage or vehicle details) if it's wrong.

[⌵ Show all sections](#)

MOT history

Check mileage recorded at test, expiry date, and test outcome

[⌶ Hide](#)

Date tested
30 September 2025

PASS

Mileage
88,016 miles

Test location

▶ [View test location](#)

MOT test number
5111 0901 7423

Expiry date
2 October 2026

Date tested
3 October 2024

PASS

Mileage
81,433 miles

Test location

▶ [View test location](#)

MOT test number
1159 5058 5250

Expiry date
2 October 2025

Monitor and repair if necessary (advisories):

- **Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Front bush (5.3.4 (a) (i))**
- **Offside Front Tyre worn close to legal limit/worn on edge Heavy wear to inner edge (5.2.3 (e))**
- **Front Exhaust has a minor leak of exhaust gases Slight blow front pipe (6.1.2 (a))**
- **Oil leak, but not excessive (8.4.1 (a) (i))**

▶ [What are advisories?](#)

Date tested
2 October 2024

FAIL

Mileage
81,433 miles

Test location

▶ [View test location](#)

MOT test number
4996 1473 4096

Repair immediately (major defects):

- **Offside Front Position lamp not working (4.2.1 (a) (ii))**
- **Offside Front Lower Suspension arm pin or bush excessively worn Front bush (5.3.4 (a) (i))**

Repair as soon as possible (minor defects):

- **Offside Front Suspension arm ball joint dust cover severely deteriorated Lower ball Joint (5.3.4 (b) (i))**

Monitor and repair if necessary (advisories):

- **Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Front bush (5.3.4 (a) (i))**
- **Offside Front Tyre worn close to legal limit/worn on edge Heavy wear to inner edge (5.2.3 (e))**
- **Front Exhaust has a minor leak of exhaust gases Slight blow front pipe (6.1.2 (a))**
- **Oil leak, but not excessive (8.4.1 (a) (i))**

▶ [What are defects and advisories?](#)

Date tested
19 September 2023

PASS

Mileage
72,629 miles

Test location
▶ [View test location](#)

MOT test number
9494 6068 4347

Expiry date
28 September 2024

Date tested
18 September 2023

FAIL

Mileage
72,629 miles

Test location
▶ [View test location](#)

MOT test number
9211 7920 6917

Repair immediately (major defects):

- **Nearside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))**

Monitor and repair if necessary (advisories):

- **Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**

▶ [What are defects and advisories?](#)

Date tested
22 September 2022

PASS

Mileage
66,976 miles

Test location
▶ [View test location](#)

MOT test number
4269 6936 8276

Expiry date
28 September 2023

Monitor and repair if necessary (advisories):

- **Rear Brake pipe corroded, covered in grease or other material x2 (1.1.11 (c))**

▶ [What are advisories?](#)

Date tested
15 September 2021

PASS

Mileage
64,627 miles

Test location
▶ [View test location](#)

MOT test number
3626 1700 1671

Expiry date
28 September 2022

Monitor and repair if necessary (advisories):

- **Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**
- **Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**
- **Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**

- **Brake pipe corroded, covered in grease or other material both front to rear at rear (1.1.11 (c))**

▶ [What are advisories?](#)

Date tested
13 September 2021

Mileage
64,626 miles

MOT test number
1195 0044 6127

FAIL

Test location

▶ [View test location](#)

Repair immediately (major defects):

- **Offside Front Anti-lock braking system component excessively damaged ABS ring burst (1.6 (e))**
- **Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**
- **Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**

Monitor and repair if necessary (advisories):

- **Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**
- **Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**
- **Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**
- **Brake pipe corroded, covered in grease or other material both front to rear at rear (1.1.11 (c))**

▶ [What are defects and advisories?](#)

Date tested
29 September 2020

Mileage
57,907 miles

MOT test number
3066 8210 2189

PASS

Test location

▶ [View test location](#)

Expiry date
28 September 2021

Date tested
24 September 2020

Mileage
57,907 miles

MOT test number
5814 7477 4331

FAIL

Test location

▶ [View test location](#)

Repair immediately (major defects):

- **Offside Rear Brake pipe excessively corroded (1.1.11 (c))**
- **Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**
- **Windscreen washer not working (3.5 (a))**

[▶ What are defects?](#)

Date tested
26 September 2019

PASS

Mileage
50,736 miles

Test location

▶ [View test location](#)

MOT test number
4950 9695 9855

Expiry date
28 September 2020

Monitor and repair if necessary (advisories):

- **Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**
- **Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **dampness steering rack pinion**

▶ [What are advisories?](#)

Date tested
26 September 2019

FAIL

Mileage
50,736 miles

Test location

▶ [View test location](#)

MOT test number
9214 5116 1059

Repair immediately (major defects):

- **Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**
- **Nearside Front Anti-lock braking system component excessively damaged abs ring (1.6 (e))**

Monitor and repair if necessary (advisories):

- **Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**
- **Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **dampness steering rack pinion**

▶ [What are defects and advisories?](#)

Date tested
29 September 2018

PASS

Mileage
43,841 miles

Test location

▶ [View test location](#)

MOT test number
6604 6487 9628

Expiry date
28 September 2019

Monitor and repair if necessary (advisories):

- **Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**
- **front suspension arm bushes perished**

▶ [What are advisories?](#)

Date tested
28 September 2018

FAIL

Mileage
43,841 miles

Test location

▶ [View test location](#)

MOT test number
3244 7307 9230

Repair immediately (major defects):

- **Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**

Monitor and repair if necessary (advisories):

- **Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**
- **o/s/f tyre badly worn on inner shoulder**
- **front suspension arm bushes perished**

▶ [What are defects and advisories?](#)

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. [Find out more \(https://www.gov.uk/government/news/mot-changes-20-may-2018\)](https://www.gov.uk/government/news/mot-changes-20-may-2018).

Date tested
15 September 2017

PASS

Mileage
37,319 miles

Test location

▶ [View test location](#)

MOT test number
5568 5115 8950

Expiry date
24 September 2018

Advisory notice item(s)

- **Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear-most (2.4.G.2)**

▶ [What are advisories?](#)

Date tested
15 September 2017

FAIL

Mileage
37,319 miles

Test location

▶ [View test location](#)

MOT test number
6623 0624 5208

Reason(s) for failure

- **Front Exhaust system not adequately supported mount burst (7.1.1)**

Advisory notice item(s)

- **Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear-most (2.4.G.2)**

▶ [What are failures and advisories?](#)

Date tested
23 September 2016

PASS

Mileage
31,852 miles

Test location

▶ [View test location](#)

MOT test number
1867 7111 1715

Expiry date
24 September 2017

Date tested
22 September 2016

FAIL

Mileage
31,852 miles

Test location

▶ [View test location](#)

Reason(s) for failure

- **Offside Front Front suspension ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**

▶ [What are failures?](#)

Date tested
16 September 2015

PASS

Mileage
28,227 miles

Test location

▶ [View test location](#)

MOT test number
1024 9171 1293

Expiry date
24 September 2016

Advisory notice item(s)

- **Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**
- **Front Tips of front wiper blades torn**
- **Rear wiper blade smearing screen**

▶ [What are advisories?](#)

Date tested
23 September 2014

PASS

Mileage
23,671 miles

Test location

MOT test number
1659 5606 4255

Expiry date
24 September 2015

[▶ View test location](#)

Date tested
23 September 2014

Mileage
23,671 miles

MOT test number
2775 4626 4218

FAIL

Test location

▶ [View test location](#)

Reason(s) for failure

- **Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**
- **Offside Front Tyre has ply or cords exposed (4.1.D.1b)**

▶ [What are failures?](#)

Date tested
24 September 2013

Mileage
15,214 miles

MOT test number
4765 3786 3281

PASS

Test location

▶ [View test location](#)

Expiry date
24 September 2014

Check for vehicle recalls

See if KIA RIO SK60USP has outstanding recalls

⌵ [Show](#)



[Cookies](#) [Terms and conditions](#) [Privacy notice](#) [Accessibility statement](#)

[MOT history API](#) [Service status](#)

Built by the [Driver & Vehicle Standards Agency](#)

OGL

All content is available under the [Open Government Licence v3.0](#), except where otherwise stated

© [Crown copyright](#)